

Inspection Photos  
Location Name: Castor LC 25-72HN  
Location ID: 422133



Photo 1 – Wellhead

Photo 2 – Wellhead Sign

**Inspection Photos**  
**Location Name: Castor LC 25-72HN**  
**Location ID: 422133**



**Photo 3 – Gas Meters**

**Photo 4 – Separators**

Inspection Photos  
Location Name: Castor LC 25-72HN  
Location ID: 422133



Photo 5 – VRU

Photo 6 – Tank Battery Signs

Inspection Photos  
Location Name: Castor LC 25-72HN  
Location ID: 422133




Photo 7 – Tank Battery

Photo 8 – Content Label missing

Inspection Photos  
Location Name: Castor LC 25-72HN  
Location ID: 422133



Photo 9 – Tank Labels – NFPA and Content

Photo 10 – Tank Battery


**Inspection Photos**  
**Location Name: Castor LC 25-72HN**  
**Location ID: 422133**



**Photo 11 – Separators and Compressor**

**Photo 12 – Compressor**

**Inspection Photos**  
**Location Name: Castor LC 25-72HN**  
**Location ID: 422133**



**Photo 13 – Compressor – Stained Soil**

**Photo 14 – Compressor – Stained Soil**

Inspection Photos  
Location Name: Castor LC 25-72HN  
Location ID: 422133




Photo 15 – Compressor – Stained Soil

Photo 16 – Wildlife Netting in disrepair

Inspection Photos  
Location Name: Castor LC 25-72HN  
Location ID: 422133





Photo 17 – Compressor – Stained Soil

Photo 18 – Wildlife Netting in disrepair

**Inspection Photos**  
**Location Name: Castor LC 25-72HN**  
**Location ID: 422133**



**Photo 19 – Wildlife Netting in disrepair**