

Inspection Photos
Location Name: Kevin LC 26-748 PAD
Location ID: 440094



Photo 1 – Gas Lift Injection Meter House

Photo 2 – Wellheads

Inspection Photos
Location Name: Kevin LC 26-748 PAD
Location ID: 440094



Photo 3 – LC26-728 Wellhead – Section # not adequate –
Well PAD is in Section 26 not Section 25

Photo 4 – LC35-738 Wellhead – Section # not adequate –
Well PAD is in Section 26 not Section 25