

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PORTER FEDERAL 11-28 Pad

Location ID: 324130



Photo # 9365 From entrance to location



Photo # 9366 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PORTER FEDERAL 11-28 Pad

Location ID: 324130



Photo # 9369 Location



Photo # 9370 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PORTER FEDERAL 11-28 Pad

Location ID: 324130



Photo # 9371 Location



Photo # 9372 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PORTER FEDERAL 11-28 Pad

Location ID: 324130



Photo # 9373 Location



Photo # 9374 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PORTER FEDERAL 11-28 Pad

Location ID: 324130



Photo # 9375 Stained soils & gravel



Photo # 9376 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PORTER FEDERAL 11-28 Pad

Location ID: 324130



Photo # 9377 Open ended pipe/available for entry by wildlife/wildlife hazard



Photo # 9378 Unused equipment/ECD disconnected & not in use

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PORTER FEDERAL 11-28 Pad

Location ID: 324130



Photo # 9379 Unused equipment