



Well 35-4 Access Road from County Road 11 looking west. The Access Road had been ripped and disced by the farmer who leases the property.



Well 35-4 Access Road View approximately half way between County Road 11 and the well pad.

PREPARED BY:
WELLINGTON OPERATING CO.
WELLINGTON, COLORADO

Access Road and Well Pad Area - Photos 1
WELLINGTON OPERATING COMPANY – Well 35-4 Access Road & Pad
March 2024

PREPARED FOR:
 **COLORADO**
Oil & Gas Conservation
Commission
Department of Natural Resources



Well 35-4 well pad area looking West.



Well 35-4 well pad area looking East

PREPARED BY:
WELLINGTON OPERATING CO.
WELLINGTON, COLORADO

Access Road & Well Pad Area - Photos 2
WELLINGTON OPERATING COMPANY – Well 35-4 Access Road & Pad
March 2024

PREPARED FOR:
 **COLORADO**
Oil & Gas Conservation
Commission
Department of Natural Resources