

# Inspection Photos

Loc: 334120

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 3/11/2024

County: LAS ANIMAS



## Inspection Photos



**Photo 1.** Facing southwest toward the location. There was water from a leak that spread across the location from right to left side of photo.



Inspection Photos



**Photo 2.** Facing northwest. The leak occurred at the wellhead..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:334120 | Date: 3/11/2024

Inspection Photos



**Photo 2.** Facing east where water lwaK across the location..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:334120 | Date: 3/11/2024

Inspection Photos



**Photo 2.** Facing toward the wellhead.

