

Inspection Photos

Location Name: SLW GREEN STATE-65N63W/18NESE

Location ID: 330538



Photo #1

SLW Green State BB 18-09 (123-19257) Wellsite

Shut-In | SI



Photo #2

SLW Green State BB 18-09 Wellsite

Shut-In | SI
wellsite entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: SLW GREEN STATE-65N63W/18NESE

Location ID: 330538



Photo #3

SLW Green State BB 18-09, 18-12 Battery site

Inactive | Shut-down

Formerly served:

*SLW Green State BB 18-10, SLW Green State BB 18-11;
Plugged & Abandoned | PA*

Equipment Documented; Loc ID: 330538



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources