

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2024

Submitted Date:

03/13/2024

Document Number:

707602483

FIELD INSPECTION FORMLoc ID 330538 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251454	WELL	SI	05/01/2021	OW	123-19257	SLW GREEN STATE BB 18 -09	SI

General Comment:

This is a WELL inspection.
Well(s): 1: Shut-In | SI.
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs
(330538, 330358).
(Well(s): 1: Shut-In ; 1: Temporarily Abandoned | TA).

Centralized Battery Formerly served 2 Location IDs
(330357, 330539).
(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID
(Pending).

Reference (Associated Well(s), Battery Inspections):
A.) Field Inspection Report doc. #707602483 and/or Location ID #330538
for SI Well(s) info.
B.) Field Inspection Report doc. #707602485 and/or Location ID #330358
for TA Well(s) info.
C.) Field Inspection Report doc. #707602487 and/or Location ID #330357
for PA Well(s) info.
D.) Field Inspection Report doc. #707602489 and/or Location ID #330539
for PA Well(s) info
E.) Field Inspection Report doc. #707602491 and/or Location ID #330538
for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.396256,-104.478884
Comment:	Centralized Battery serves 2 Location IDs (330538, 330358). (Well(s): 1: Shut-In ; 1: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 251454

Type: WELL

API Number: 123-19257

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: PRODUCTION RECORDS

Comment:

Shut-In | SI.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied at well, separator.
CECMC records last production: 04/2021.

Form 6A on file. Out-of-Svc Designation.
Date: 04/07/20221. Approved.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/16/2023

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 5

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On THU 03/07/2024 at approximately 15:30 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: SLW GREEN STATE-65N63W/18NESE Location ID: 330538 Well Name(s): SLW Green State BB 18-09. API: 123-19257. Location County: Weld County, Colorado Weather: Mostly Cloudy, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	03/13/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602484	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6465643