

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/07/2024

Submitted Date:

03/13/2024

Document Number:

707602485

FIELD INSPECTION FORM

Loc ID 330358 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251160	WELL	TA	02/01/2017	OW	123-18963	SLW GREEN STATE BB 18 -12	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (330538, 330358).
(Well(s): 1: Shut-In ; 1: Temporarily Abandoned | TA).

Centralized Battery Formerly served 2 Location IDs (330357, 330539).
(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):
A.) Field Inspection Report doc. #707602483 and/or Location ID #330538 for SI Well(s) info.
B.) Field Inspection Report doc. #707602485 and/or Location ID #330358 for TA Well(s) info.
C.) Field Inspection Report doc. #707602487 and/or Location ID #330357 for PA Well(s) info.
D.) Field Inspection Report doc. #707602489 and/or Location ID #330539 for PA Well(s) info
E.) Field Inspection Report doc. #707602491 and/or Location ID #330538 for Battery / Facility, Equipment info.

Location

Lease Road:

	Type Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:

			corrective date
Type: Bradenhead # 1			
Comment: Appears plumbed to surface.			
Corrective Action:			Date:
Type: Other # 1			
Comment: Wellhead: w/ Master, casing valves.			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.396256,-104.478884
Comment:	Centralized Battery serves 2 Location IDs (330538, 330358). (Well(s): 1: Shut-In ; 1: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 251160 Type: WELL API Number: 123-18963 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied at well, separator.
Blue TA tag posted.
CECMC records last production: 04/2015.

Form 4 on file. TA date: 04/20/2015. Approved.
DH-RBP set.
Form 21 MIT on file. MIT date: 01/25/2019. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 04/12/2015. Approved.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 08/15/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On THU 03/07/2024 at approximately 14:17 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: SLW GREEN STATE BB-65N63W/18NWSW Location ID: 330358 Well Name(s): SLW Green State BB 18-12. API: 123-18963. Location County: Weld County, Colorado Weather: Mostly Cloudy, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	03/13/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602486	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6465644