

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/07/2024

Submitted Date:

03/13/2024

Document Number:

707602487

**FIELD INSPECTION FORM**

Loc ID: 330357  
Inspector Name: Evins, Bret  
On-Site Inspection:   
2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**  
OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 2001 16TH STREET SUITE 900  
City: DENVER State: CO Zip: 80202

**Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251159	WELL	TA	02/01/2017	OW	123-18962	SLW GREEN STATE BB 18-11	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (330538, 330358).  
(Well(s): 1: Shut-In ; 1: Temporarily Abandoned | TA).

Centralized Battery Formerly served 2 Location IDs (330357, 330539).  
(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):  
A.) Field Inspection Report doc. #707602483 and/or Location ID #330538 for SI Well(s) info.  
B.) Field Inspection Report doc. #707602485 and/or Location ID #330358 for TA Well(s) info.  
C.) Field Inspection Report doc. #707602487 and/or Location ID #330357 for PA Well(s) info.  
D.) Field Inspection Report doc. #707602489 and/or Location ID #330539 for PA Well(s) info.  
E.) Field Inspection Report doc. #707602491 and/or Location ID #330538 for Battery / Facility, Equipment info.

**Inspected Facilities**

Facility ID: 251159 Type: WELL API Number: 123-18962 Status: TA Insp. Status: PA

**COGCC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On THU 03/07/2024 at approximately 16:21 hrs. I, Bret Evins, conducted an onsite inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: SLW GREEN STATE BB-65N63W/18NESW                      Location ID: 330357                      Well Name(s):                      SLW Green State BB 18-11.                      API:                      123-18962.                      Location County: Weld County, Colorado                      Weather: Mostly Cloudy, damp from prior storm.</p> <p>While there, I observed:                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Battery: Inactive   Shut-down.</p> <p><b>WELL STATUS COMMENT:</b>                      Plugged &amp; Abandoned   PA.                      Form 4 PA Notice on file. Date: 03/04/2024. Approved.                      Form 6-Notice of Intent to Abandon on file. Date: 02/07/2024. Approved.                      Plugging, surface plug date: 03/07/2024. NOT cut/capped.                      Plugged &amp; Abandoned   PA well GPS coordinates: 40.397357 / -104.481403</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	03/13/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602488	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6465645">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6465645</a>