

**Inspection Photos**  
**Location Name: Milton H Nelson Unit B 1**  
**Location ID: 336292**



**Photo 1 Location.**



**Photo 2 Disassembled pump jack parts.**

Inspection Photos  
Location Name: Milton H Nelson Unit B 1  
Location ID: 336292



Photo 3 WH, monitoring equipment & sign.



Photo 4 WH sign.

**Inspection Photos**  
**Location Name: Milton H Nelson Unit B 1**  
**Location ID: 336292**



**Photo 5 Disassembled pump jack.**



**Photo 6 Disassembled pump jack parts, electric panel.**

**Inspection Photos**  
**Location Name: Milton H Nelson Unit B 1**  
**Location ID: 336292**



**Photo 7 Disassembled pump jack no electric motor.**



**Photo 8 Electric panel is shut off transformers are gone.**

**Inspection Photos**  
**Location Name: Milton H Nelson Unit B 1**  
**Location ID: 336292**



**Photo 9 Disassembled pump jack.**