

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JACKSON 9-28 Pad

Location ID: 335347



Photo # 9411 From entrance to location



Photo # 9412 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JACKSON 9-28 Pad

Location ID: 335347



Photo # 9413 Location



Photo # 9414 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JACKSON 9-28 Pad

Location ID: 335347



Photo # 9416 Location



Photo # 9417 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JACKSON 9-28 Pad

Location ID: 335347



Photo # 9418 Unused equipment/ECD disconnected & not in use



Photo # 9419 Unused equipment/ECD disconnected & not in use



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JACKSON 9-28 Pad

Location ID: 335347



Photo # 9420 Unmarked deadman




Photo # 9421 Tank label peeling & some information not visible



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JACKSON 9-28 Pad

Location ID: 335347




Photo # 9422 Tank label peeling & some information not visible




Photo # 9423 Tank label peeling & some information not visible



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JACKSON 9-28 Pad

Location ID: 335347



Photo # 9424 Debris



Photo # 9425 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JACKSON 9-28 Pad

Location ID: 335347




Photo # 9426 Tank label weathered & becoming illegible



Photo # 9427 Well API # obscured by emergency # sticker