

Inspection Photos


Location Name: LARAMIE ENERGY LLC, NVega Pad/5A

Location ID: 334486

Date: 3/12/2024



Location Entrance – Photo #09787



Wellheads – Photo #09788

Inspection Photos

Location Name: LARAMIE ENERGY LLC, NVega Pad/5A

Location ID: 334486

Date: 3/12/2024



Separators – Photo #09793



Tank Battery – Photo #09789

Inspection Photos

Location Name: LARAMIE ENERGY LLC, NVega Pad/5A

Location ID: 334486

Date: 3/12/2024



Lack of Stabilization – Photo #09795



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09796**