

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STRANAHAN 41C-27 Pad

Location ID: 335437



Photo # 9684 From entrance to location



Photo # 9685 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STRANAHAN 41C-27 Pad

Location ID: 335437



Photo # 9686 Location



Photo # 9687 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STRANAHAN 41C-27 Pad

Location ID: 335437



Photo # 9688 Location



Photo # 9689 Unused equipment/ECD disconnected & not in use

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STRANAHAN 41C-27 Pad

Location ID: 335437



Photo # 9690 Tank label damaged & some required info illegible/does not comply with CECMC tank labeling rules




Photo # 9691 Wellhead sign faded & illegible

