

# Inspection Photos

Loc: 309123

Operator: OGRIS OPERATING LLC

Inspection Date: 3/13/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northwest toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:309123 | Date: 3/13/2024



## Inspection Photos



**Photo 2.** The water discharge point just west of the well is not maintained. The plastic liner is pulled up. The electric fence is in disrepair. T-post and fence should either be removed or maintained.

