

# Inspection Photos

Loc: 309138

Operator: OGRIS OPERATING LLC

Inspection Date: 3/13/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos



**Photo 1.** Facing east toward the wellsite.



## Inspection Photos



**Photo 2.** Facing toward the wellsite. The fence around the pit has been replaced with wire. Stained soils have been cleaned up.

