

Inspection Photos

Loc: 308613

Operator: OGRIS OPERATING LLC

Inspection Date: 3/13/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308613 | Date: 3/13/2024

Inspection Photos



Photo 2. Well sign is posted at meter shed.



Inspection Photos



Photo 3. The stained soil previously observed has been cleaned up and unused parts have been removed..

