

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, NVega/2B Pad

Location ID: 334465

Date: 3/12/2024



Location Entrance – Photo #09829



Wellheads – Photo #09834

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, NVega/2B Pad

Location ID: 334465

Date: 3/12/2024



**Separators – Photo #09839**



**Tank Battery – Photo #09830**





## Inspection Photos

Location Name: LARAMIE ENERGY LLC, NVega/2B Pad

Location ID: 334465

Date: 3/12/2024



Unprotected Soil Stockpile – Photo #09835



Unprotected Soil Stockpile – Photo #09836

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, NVega/2B Pad

Location ID: 334465

Date: 3/12/2024



**Lack of Stabilization – Photo #09838**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #09840**