

Inspection Photos

Location Name: LARAMIE ENERGY LLC, NVega/3A Pad

Location ID: 334487

Date: 3/12/2024



Location Entrance – Photo #09867



Wellheads – Photo #09869

Inspection Photos

Location Name: LARAMIE ENERGY LLC, NVega/3A Pad

Location ID: 334487

Date: 3/12/2024



Separators – Photo #09870



Tank Battery – Photo #09871

Inspection Photos

Location Name: LARAMIE ENERGY LLC, NVega/3A Pad

Location ID: 334487

Date: 3/12/2024



Lack of Stabilization – Photo #09868



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09873**