

Caerus
B8E
Location ID: 334786



Location



Location

Caerus
B8E
Location ID: 334786



Location



Location

Caerus
B8E
Location ID: 334786



Location



Battery signage has 2 wells not on location

Caerus
B8E
Location ID: 334786



Location culvert outlet



Location culvert inlet

Caerus
B8E
Location ID: 334786



Lack of compaction/ stabilization



Lack of compaction/ stabilization

Caerus
B8E
Location ID: 334786



Lacking tracking BMP's



Lacking tracking BMP's

Caerus
B8E
Location ID: 334786



Debris



BMP's failing

Caerus
B8E
Location ID: 334786



BMP's failing