

Caerus
J17E
Location ID: 334872



Location



Location

Caerus
J17E
Location ID: 334872



Location



Graveled entrance

Caerus
J17E
Location ID: 334872



Fencing around contaminated excavation is open



Fencing around contaminated excavation is down

Caerus
J17E
Location ID: 334872



Fencing around contaminated excavation is down



Debris

Caerus
J17E
Location ID: 334872



Unused equipment



Unused equipment