

Final Reclamation Inspection

March 12th, 2024

Operator: Logos Operating LLC - 10679

Location ID: 325194

Inspection Document #: 714000542

La Plata County, CO

Township: NWSE 14 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-10 17
Location ID: 325194

3/12/24
+37.101013,-107.900746
345° N



Photo 1. Overview of the disturbance taken from the entrance facing center.



Inspection Photos
Location Name: Bondad 33-10 17
Location ID: 325194



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the eastern interim reclamation area facing north.
Vegetation comprised of western wheat and smooth brome.

API #: 067-05588

Inspection Photos
Location Name: Bondad 33-10 17
Location ID: 325194



Photo 3. View of un marked guy line anchor observed on location.

Inspection Photos
Location Name: Bondad 33-10 17
Location ID: 325194



Photo 4. View of the reference area comprised of smooth brome, rabbit brush and sage brush.