

Final Reclamation Inspection

March 12th, 2024

Operator: Enduring Resources LLC - 10663

Location ID: 333788

Inspection Document #: 714000544

La Plata County, CO

Township: NWSE 24 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ute C 1, C 3
Location ID: 333788




Photo 1. Overview of the disturbance taken from the entrance facing center.

Inspection Photos
Location Name: Ute C 1, C 3
Location ID: 333788



3/12/24
+37.087001,-107.883053
165° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the western interim reclamation area facing south.

API #: 067-05584, 07644

Inspection Photos
Location Name: Ute C 1, C 3
Location ID: 333788



Photo 3. View of weedy kochia debris that remain on location.



Inspection Photos
Location Name: Ute C 1, C 3
Location ID: 333788



Photo 4. View of impacted surface material at the compressor.

