

# Final Reclamation Inspection

March 12th, 2024

Operator: Simcoe LLC = 107409

Location ID: 333515

Inspection Document #: 714000547

La Plata County, CO

Township: NESW 19 33N 9W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Koon 1E  
Location ID: 333515




Photo 1. Overview of the disturbance taken from the entrance facing center.



API #: 067-06331

Inspection Photos  
Location Name: Koon 1E  
Location ID: 333515



**Photo 2.** View of impacted surface material at active equipment on location.

Inspection Photos  
Location Name: Koon 1E  
Location ID: 333515



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** View of Simcoe produced water sign that is deteriorating and illegible.

API #: 067-06331

Inspection Photos  
Location Name: Koon 1E  
Location ID: 333515

3/12/24  
+37.086510,-107.870897  
191° S



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** View of the western interim reclamation area facing south.  
Vegetation comprised of smooth brome, rabbit brush and sage brush.

API #: 067-06331

Inspection Photos  
Location Name: Koon 1E  
Location ID: 333515

3/12/24  
+37.086612,-107.870878  
330° NW

