

Storm Water Management and Erosion control

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF03B19 D19A 595 Pad

Location # 335905



Location Overview: Location is within High Priority/Density/NSO/Black Bear Habitat areas. Location is approximately 83 yards from East Middle Fork Parachute Creek.

Section/Township/Range: 19 5S95W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF03B19 D19A 595 Pad
Location # 335905



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF03B19 D19A 595 Pad

Location # 335905



Photo # 90 Chemical containment approximately 3/4th full of fluid/Failure to maintain chemical BMP/BMP insufficient to contain possible spill



Photo # 91 Chemical containment approximately 5/8th to 3/4th full of fluid/Failure to maintain chemical BMP/BMP insufficient to contain possible spill