

# Final Reclamation Inspection

March 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333834

Inspection Document #: 714000556

La Plata County, CO

Township: NENE 25 33N 10W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Sharp 3E  
Location ID: 333834



Photo 1. Overview of the disturbance taken from the entrance facing center.



API #: 067-06668

Inspection Photos  
Location Name: Sharp 3E  
Location ID: 333834

3/12/24  
+37.079545,-107.878280  
132° SE



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the eastern interim reclamation area facing south east.  
Vegetation comprised of smooth brome.

API #: 067-06668

Inspection Photos  
Location Name: Sharp 3E  
Location ID: 333834



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Produced water sign corrective action identified in the previous inspection doc #712700811 has been addressed.

API #: 067-06668

Inspection Photos  
Location Name: Sharp 3E  
Location ID: 333834

3/12/24  
+37.079545,-107.878280  
329° NW



**Photo 5.** Reference area comprised of smooth brome.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06668