

# Final Reclamation and Stormwater Inspection

March 4, 2024

Operator: Petro- Canada Resources Inc- #72085

Location ID: 311664

Inspection Document #: 709400859

Adams County, CO

SWNW Section 24 T3S R59W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Noonan Michael 1  
Location ID: 311664



**Photo 1.** Photo taken facing northwest of perimeter fence and weeds (Russian thistle & Kochia). Weeds indicated by yellow arrow.



**Photo 2.** Photo taken facing west of reclamation area vegetation and weeds (Russian thistle). Weeds indicated by yellow arrow.



Inspection Photos  
Location Name: Noonen Michael 1  
Location ID: 311664



**Photo 3.** Photo taken facing northwest of reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.




**Photo 4.** Photo taken facing north of reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.

Inspection Photos  
Location Name: Noonan Michael 1  
Location ID: 311664



**Photo 5.** Photo taken facing northeast of reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.



**Photo 6.** Photo taken facing east of reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.

Inspection Photos

Location Name: Noonan Michael 1

Location ID: 311664



**Photo 7.** Photo taken facing west of reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.



**Photo 8.** Photo taken facing northeast of reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.

Inspection Photos

Location Name: Noonan Michael 1

Location ID: 311664



**Photo 9.** Photo taken facing east of reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.

**Photo 10.** Photo taken facing east of reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.




Inspection Photos

Location Name: Noonan Michael 1

Location ID: 311664



**Photo 11.** Photo taken facing southeast of reclamation area of vegetation and weeds (russian thistle & kochia) and bare soil. Weeds indicated by yellow arrow, Red arrow indicates bare soil.



**Photo 12.** Photo taken facing south of reclamation area of vegetation and weeds (russian thistle & kochia) and bare soil. Weeds indicated by yellow arrow, Red arrow indicates bare soil.



Inspection Photos  
Location Name: Noonan Michael 1  
Location ID: 311664



**Photo 13.** Photo taken facing southwest of native vegetation for reference.

Inspection Photos

Location Name: Noonan Michael 1

Location ID: 311664



**Photo 14.** Photo taken facing south of rutted access road.

**Photo 15.** Photo taken facing northwest of rutted access road.