

Final Reclamation and Stormwater Inspection

March 4, 2024

Operator: Petro- Canada Resources Inc- #72085

Location ID: 376781

Inspection Document #: 709400861

Adams County, CO

NENW Section 24 T3S R59W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Downing B 1
Location ID: 376781



Photo 1. Photo taken facing northeast of perimeter fence of reclaimed access road. The access road meet final reclamation standards of 80% native vegetation, weed management will need to continue.



Photo 2. Photo taken facing northeast of reclaimed access road. The access road meet final reclamation standards of 80% native vegetation, weed management will need to continue.

Inspection Photos
Location Name: Downing B 1
Location ID: 376781



Photo 3. Photo taken facing east of reclaimed pad perimeter fence, vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.




Photo 4. Photo taken facing north of reclaimed pad area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.

Inspection Photos
Location Name: Downing B 1
Location ID: 376781



Photo 5. Photo taken facing southeast of reclamation area of vegetation and weeds (russian thistle, bull thistle & kochia). Weeds indicated by yellow arrow.



Photo 6. Photo taken facing southwest of pad reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.

Inspection Photos
Location Name: Downing B 1
Location ID: 376781




Photo 7. Photo taken facing west of pad reclamation area of vegetation and weeds (russian thistle, bull thistle & kochia). Weeds indicated by yellow arrow.



Photo 8. Photo taken facing northeast of close up of weeds (bull thistle).

Inspection Photos
Location Name: Downing B 1
Location ID: 376781



Photo 9. Photo taken facing east of pad reclamation area of vegetation and weeds (russian thistle, bull thistle & kochia). Weeds indicated by yellow arrow.



Photo 10. Photo taken facing west of pad reclamation area of bare soil, vegetation and weeds (russian thistle, bull thistle & kochia). Weeds indicated by yellow arrow, Red arrow indicates bare soil.

Inspection Photos
Location Name: Downing B 1
Location ID: 376781



Photo 11. Photo taken facing southwest of pad reclamation area of vegetation and weeds (russian thistle & kochia) and cut slope not recontoured to native landscape (indicated by red arrow).



Photo 12. Photo taken facing southwest of pad reclamation area of vegetation and weeds (russian thistle & kochia) and cut slope not recontoured to native landscape (indicated by red arrow).



Photo 13. Photo taken facing southwest of native vegetation for reference.

Inspection Photos
Location Name: Downing B 1
Location ID: 376781



Photo 14. Photo taken facing south of rutted access road.



Photo 15. Photo taken facing northwest of rutted access road.