

# Final Reclamation and Stormwater Inspection

March 4, 2024

Operator: Oilfield Salvage & Service Co- #65550

Location ID: 311709

Inspection Document #: 709400867

Adams County, CO

NWNW Section 18 T3S R59W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Noonan Ranch 10  
Location ID: 311709




**Photo 1.** Photo taken facing southeast of reclaimed area.



**Photo 2.** Photo taken facing south of pad reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.

Inspection Photos  
Location Name: Noonan Ranch 10  
Location ID: 311709



**Photo 3.** Photo taken facing south of reclamation area of vegetation, weeds (russian thistle & kochia) and bare soil. Weeds indicated by yellow arrow, bare soil indicated by red arrow.



**Photo 4.** Photo taken facing south of reclamation area of vegetation, weeds (russian thistle & kochia) and bare soil. Weeds indicated by yellow arrow, bare soil indicated by red arrow.



Inspection Photos  
Location Name: Noonan Ranch 10  
Location ID: 311709



**Photo 5.** Photo taken facing southeast of reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.



**Photo 6.** Photo taken facing northeast of reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.


## Inspection Photos

Location Name: Noonan Ranch 10

Location ID: 311709



**Photo 7.** Photo taken facing southwest of reclamation area of vegetation, weeds (russian thistle & kochia) and bare soil. Weeds indicated by yellow arrow, bare soil indicated by red arrow.



**Photo 8.** Photo taken facing southwest of pad reclamation area of vegetation, weeds (russian thistle & kochia) and bare soil. Weeds indicated by yellow arrow, bare soil indicated by red arrow.



Inspection Photos  
Location Name: Noonan Ranch 10  
Location ID: 311709



**Photo 9.** Photo taken facing south of reclamation area of vegetation, weeds (russian thistle & kochia) and bare soil. Weeds indicated by yellow arrow, bare soil indicated by red arrow.




**Photo 10.** Photo taken facing south of reclamation area of vegetation, bare soil and stormwater erosion under BMP. Bare soil indicated by red arrow.

Inspection Photos

Location Name: Noonan Ranch 10

Location ID: 311709



**Photo 11.** Photo taken facing north of pad reclamation area of vegetation and bare soil. Bare soil indicated by red arrow.

**Photo 12.** Photo taken facing north of pad reclamation area of vegetation and weeds (russian thistle & kochia) and bare soil. Weeds indicated by yellow arrow, bare soil indicated by red arrow.



Inspection Photos  
Location Name: Noonan Ranch 10  
Location ID: 311709



**Photo 13.** Photo taken facing southwest of native vegetation for reference.

Inspection Photos

Location Name: Noonan Ranch 10

Location ID: 311709



**Photo 14.** Photo taken facing south of rutted access road.

**Photo 15.** Photo taken facing northwest of rutted access road.



Inspection Photos

Location Name: Noonan Ranch 10

Location ID: 311709



Mar 4, 2024 at 12:07:44 PM  
Byers CO 80103  
United States



Mar 4, 2024 at 12:08:01 PM  
Byers CO 80103  
United States

**Photo 16.** Photo taken facing southwest of rutted access road with stormwater erosion..

**Photo 17.** Photo taken facing northwest of rutted access road with stormwater erosion. .

