

Interim Reclamation and Stormwater Inspection

March 11 , 2024

Operator: Wiepking Fullerton Energy LLC- #96340

Location ID: 387137

Inspection Document #: 709400876

Lincoln County, CO

NESW Section 6 T10S R55W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: State Monk 23-6 #1
Location ID: 387137



Photo 1. Photo taken of location sign.



Photo 2. Photo taken facing northwest of well head.



Inspection Photos
Location Name: State Monk 23-6 #1
Location ID: 387137



Photo 3. Photo taken facing northwest of tank battery on site.




Photo 4. Photo taken facing southwest of reclamation area of vegetation, weeds (russian thistle & kochia). Weeds indicated by yellow arrow.

Inspection Photos
Location Name: State Monk 23-6 #1
Location ID: 387137



Photo 5. Photo taken facing north of reclamation area of vegetation and weeds (Russian thistle & Kochia). Weeds indicated by yellow arrow.



Photo 6. Photo taken facing northwest of reclamation area of vegetation and weeds (Russian thistle & Kochia). Weeds indicated by yellow arrow.



Inspection Photos
Location Name: State Monk 23-6 #1
Location ID: 387137



Photo 7. Photo taken facing southwest of wellhead and staining of soil.



Photo 8. Photo taken facing west of stained soil around wellhead.

Inspection Photos
Location Name: State Monk 23-6 #1
Location ID: 387137



Photo 9. Photo taken facing north of secondary containment lacking wildlife protection, indicated by yellow arrow.



Photo 10. Photo taken facing southeast of unused equipment on site, indicated by yellow arrow.

Inspection Photos
Location Name: State Monk 23-6 #1
Location ID: 387137



Photo 11. Photo taken facing east of pad reclamation area of mowed vegetation.



Photo 12. Photo taken facing south of pad reclamation area vegetation.

Inspection Photos
Location Name: State Monk 23-6 #1
Location ID: 387137



Photo 13. Photo taken facing north of interim reclamation area.



Photo 14. Photo taken facing west of interim reclamation area.