

# Final Reclamation and Stormwater Inspection

March 4, 2024

Operator: Petro- Canada Resources Inc- #72085

Location ID: 311698

Inspection Document #: 709400879

Adams County, CO

SWSW Section 213 T3S R59W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Noonan UPRR 2-B  
Location ID: 311698



Mar 4, 2024 at 11:17:58 AM

**Photo 1.** Photo taken facing northeast of perimeter fence of reclaimed area vegetation and weeds (koachia & russian thistle).



Mar 4, 2024 at 11:18:25 AM

**Photo 2.** Photo taken facing northeast of perimeter fence of reclaimed area vegetation and weeds (koachia & russian thistle). Weeds indicated by yellow arrow.



Inspection Photos  
Location Name: Noonan UPRR 2-B  
Location ID: 311698



**Photo 3.** Photo taken facing east of reclaimed area vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.



**Photo 4.** Photo taken facing north of close up of weeds (russian thistle & bull thistle).





Inspection Photos  
Location Name: Noonan UPRR 2-B  
Location ID: 311698



**Photo 5.** Photo taken facing southeast of reclamation area of vegetation and weeds (russian thistle, bull thistle & kochia). Weeds indicated by yellow arrow.



**Photo 6.** Photo taken facing southeast of pad reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.



Inspection Photos  
Location Name: Noonan UPRR 2-B  
Location ID: 311698



Mar 4, 2024 at 11:22:00 AM  
Byers CO 80103  
United States

**Photo 7.** Photo taken facing west of pad reclamation area of vegetation and weeds (russian thistle, bull thistle & kochia). Weeds indicated by yellow arrow.



Mar 4, 2024 at 11:22:37 AM  
Byers CO 80103  
United States

**Photo 8.** Photo taken facing southeast of weeds and bare soil (red arrow) in reclaimed area. Red arrow of bare soil is an example of bare area from salt kill. Weeds indicated by yellow arrow.



Inspection Photos  
Location Name: Noonan UPRR 2-B  
Location ID: 311698



Mar 4, 2024 at 11:22:43 AM  
Byers CO 80103  
United States



Mar 4, 2024 at 11:22:50 AM

**Photo 9.** Photo taken facing east of weeds (russian thistle, & kochia)( yellow arrow) and bare soil (Red arrow) in reclaimed area.


**Photo 10.** Photo taken facing east of weeds (russian thistle, & kochia)( yellow arrow) and bare soil (Red arrow) in reclaimed area. Red arrow indicating bare soil is an example of bare area from salt kill.



Inspection Photos  
Location Name: Noonan UPRR 2-B  
Location ID: 311698



**Photo 11.** Photo taken facing west of weeds (russian thistle, & kochia)( yellow arrow) and bare soil (Red arrow) in reclaimed area. Red arrow indicating bare soil is an example of bare area from salt kill.



**Photo 12.** Photo taken facing northwest of reclaimed access road area of vegetation and weeds (russian thistle & kochia) Yellow arrow indicates the weeds .





Inspection Photos  
Location Name: Noonan UPRR 2-B  
Location ID: 311698



**Photo 13.** Photo taken facing southwest of access road to pad reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.



**Photo 14.** Photo taken facing southwest of pad reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.





Inspection Photos  
Location Name: Noonan UPRR 2-B  
Location ID: 311698



Mar 4, 2024 at 11:29:24 AM  
Byers CO 80103  
United States



Mar 4, 2024 at 11:29:26 AM  
Byers CO 80103  
United States

**Photo 15.** Photo taken facing northwest of reclaimed access road area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.

**Photo 16.** Photo taken facing southwest of pad reclamation area of vegetation and weeds (russian thistle & kochia). Weeds indicated by yellow arrow.



Inspection Photos  
Location Name: Noonan UPRR 2-B  
Location ID: 311698



**Photo 17.** Photo taken facing southeast of pad reclamation area of vegetation and weeds (russian thistle, kochia & cheatgrass). Weeds indicated by yellow arrow.



**Photo 18.** Photo taken facing southeast of pad reclamation area of vegetation and weeds (russian thistle, kochia & cheatgrass). Weeds indicated by yellow arrow.







**Photo 19.** Photo taken facing southwest of native vegetation for reference.



Inspection Photos  
Location Name: Noonan UPRR 2-B  
Location ID: 311698



**Photo 20.** Photo taken facing south of rutted access road.



**Photo 21.** Photo taken facing northwest of rutted access road.