

Interim Reclamation and Stormwater Inspection

March 11 , 2024

Operator: Wiepking Fullerton Energy LLC- #96340

Location ID: 431780

Inspection Document #: 709400883

Lincoln County, CO

SWNE Section 18 T10S R55W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Raptor #6
Location ID: 431780



Photo 1. Photo taken of location sign.



Photo 2. Photo taken facing north of well head.



Inspection Photos
Location Name: Raptor #6
Location ID: 430215




Photo 3. Photo taken facing northwest of Staining around wellhead.



Photo 4. Photo taken facing northw of reclamation area of mowed vegetation.



Inspection Photos
Location Name: Raptor #6
Location ID: 431780



Photo 5. Photo taken facing northeast of reclamation area of mowed vegetation around wellhead.



Photo 6. Photo taken facing east of stained soil next to pumpjack.

Inspection Photos
Location Name: Raptor #6
Location ID: 431780



Photo 7. Photo taken facing west of stained soil next to pumpjack.



Photo 8. Photo taken facing southeast of vegetation in interim reclamation area.

Inspection Photos
Location Name: Raptor #6
Location ID: 431780



Photo 9. Photo taken facing northwest of tank battery sign off site.



Photo 10. Photo taken facing southwest of tank battery.