

# Interim Reclamation and Stormwater Inspection

March 11 , 2024

Operator: Wiepking Fullerton Energy LLC- #96340

Location ID: 431490

Inspection Document #: 709400885

Lincoln County, CO

NWSE Section 18 T10S R55W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Raptor #7  
Location ID: 431490



**Photo 1.** Photo taken of location sign.



**Photo 2.** Photo taken facing east of wellhead.



**Inspection Photos**  
**Location Name: Raptor #7**  
**Location ID: 431490**



**Photo 3.** Photo taken facing northwest of staining around wellhead.



**Photo 4.** Photo taken facing north of reclamation area of mowed vegetation.



Inspection Photos  
Location Name: Raptor #7  
Location ID: 431490



Mar 11, 2024 at 12:19:25 PM  
46011 County Road 26  
Limon CO 80828  
United States



Mar 11, 2024 at 12:19:48 PM  
46011 County Road 26  
Limon CO 80828  
United States

**Photo 5.** Photo taken facing northeast of reclamation area of mowed vegetation around wellhead.

**Photo 6.** Photo taken facing east of vegetation in interim reclamation area.

Inspection Photos  
Location Name: Raptor #7  
Location ID: 431490



**Photo 7.** Photo taken facing east of vegetation in interim reclamation area.



**Photo 8.** Photo taken facing west of mowed vegetation in interim reclamation area.

Inspection Photos  
Location Name: Raptor #7  
Location ID: 431490



**Photo 9.** Photo taken facing northwest of tank battery sign off site.



**Photo 10.** Photo taken facing southwest of tank battery.