

Interim Reclamation and Stormwater Inspection

March 11 , 2024

Operator: Wiepking Fullerton Energy LLC- #96340

Location ID: 427985

Inspection Document #: 709400887

Lincoln County, CO

NWSW Section 17 T10S R55W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Napali #6
Location ID: 427985



Photo 1. Photo taken of location sign.



Photo 2. Photo taken facing north of wellhead.



Inspection Photos
Location Name: Napali #6
Location ID: 427985



Photo 3. Photo taken facing northwest of staining around wellhead.



Photo 4. Photo taken facing east of secondary containment without wildlife protection.

Inspection Photos
Location Name: Napali #6
Location ID: 427985



Photo 5. Photo taken facing northwest of reclamation area of mowed vegetation along access road.



Photo 6. Photo taken facing east of mowed vegetation in interim reclamation area.

Inspection Photos
Location Name: Napali #6
Location ID: 427985



Photo 7. Photo taken facing east of vegetation in interim reclamation area.



Photo 8. Photo taken facing west of mowed vegetation in interim reclamation area.