

# Interim Reclamation and Stormwater Inspection

March 11 , 2024

Operator: Wiepking Fullerton Energy LLC- #96340

Location ID: 420531

Inspection Document #: 709400890

Lincoln County, CO

SESW Section 17 T10S R55W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Napali #2  
Location ID: 420531



Photo 1. Photo taken of location sign.



Photo 2. Photo taken facing north of wellhead.



**Inspection Photos**  
**Location Name: Napali #2**  
**Location ID: 420531**



**Photo 3.** Photo taken facing northwest of staining around wellhead.



**Photo 4.** Photo taken facing east of secondary containment without wildlife protection.



Inspection Photos  
Location Name: Napali #2  
Location ID: 420531



**Photo 5.** Photo taken facing northwest of reclamation area of mowed vegetation.



**Photo 6.** Photo taken facing east of mowed vegetation in interim reclamation area.

Inspection Photos  
Location Name: Napali #2  
Location ID: 420531



**Photo 7.** Photo taken facing east of mowed vegetation in interim reclamation area.



**Photo 8.** Photo taken facing west of mowed vegetation in interim reclamation area.

Inspection Photos  
Location Name: Napali #2  
Location ID: 420531



Photo 9. Photo taken facing east of Tank battery sign



Photo 10. Photo taken facing east of tank battery.