

Interim Reclamation and Stormwater Inspection

March 11 , 2024

Operator: Wiepking Fullerton Energy LLC- #96340

Location ID: 427909

Inspection Document #: 709400903

Lincoln County, CO

NWSE Section 17 T10S R55W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Napali #5
Location ID: 427909



Photo 1. Photo taken of location sign.



Photo 2. Photo taken facing southeast of wellhead.



Inspection Photos
Location Name: Napali #5
Location ID: 427909



Photo 3. Photo taken facing northeast of staining around wellhead.



Photo 4. Photo taken facing east of mowed vegetation in interim reclamation area.

Inspection Photos
Location Name: Napali #5
Location ID: 427909



Photo 5. Photo taken facing northwest of reclamation area of vegetation.



Photo 6. Photo taken facing east of vegetation in interim reclamation area.

Inspection Photos
Location Name: Napali #5
Location ID: 427909



Photo 7. Photo taken facing east of vegetation in interim reclamation area.

Photo 8. Photo taken facing southeast of fenced off risers.

Inspection Photos
Location Name: Napali #5
Location ID: 427909



Photo 9. Photo taken facing east of Tank battery sign



Photo 10. Photo taken facing east of tank battery.

Inspection Photos
Location Name: Napali #5
Location ID: 427909



Photo 9. Photo taken facing east of Tank battery interim reclamation mowed vegetation.



Photo 10. Photo taken facing north of tank battery access road and stained soil.