

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BBC 12A-24 Pad

Location ID: 335442



Mar 11, 2024 at 11:40:53 AM
CO



Mar 11, 2024 at 11:57:43 AM
CO

Photo # 9177 From entrance to location

Photo # 9178 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BBC 12A-24 Pad

Location ID: 335442



Photo # 9179 Location



Photo # 9180 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BBC 12A-24 Pad

Location ID: 335442



Photo # 9181 Location



Photo # 9182 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BBC 12A-24 Pad

Location ID: 335442



Photo # 9183 Unused equipment



Photo # 9184 Unused equipment/ECD disconnected & not in use



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BBC 12A-24 Pad

Location ID: 335442



Photo # 9185 PRV vent lines lack caps/do not comply with CECMC pressure safety device rules




Photo # 9186 PRV & rupture disc vent lines lack caps/do not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BBC 12A-24 Pad

Location ID: 335442



Photo # 9187 PRV vent line on tank burner terminates in an unsafe manner/does not comply with CECMC pressure safety device rules & general safety rules.



Photo # 9188 PRV vent line on tank burner terminates in an unsafe manner/does not comply with CECMC pressure safety device rules & general safety rules.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BBC 12A-24 Pad

Location ID: 335442



Photo # 9189 PRV vent line on tank burner terminates in an unsafe manner/does not comply with CECMC pressure safety device rules & general safety rules.




Photo # 9190 Tank label damaged & missing required information

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BBC 12A-24 Pad

Location ID: 335442



Photo # 9191 Tank label damaged & missing required information




Photo # 9192 Tank label damaged & missing required information



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BBC 12A-24 Pad

Location ID: 335442



Photo # 9193 PRV Stained gravel



Photo # 9194 Stained gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BBC 12A-24 Pad

Location ID: 335442



Photo # 9195 Stained gravel



Photo # 9196 Stained gravel