

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: North Platte T-27 Pad

Loc ID: 441915

Inspection: 708200986



Exhibit A



Exhibit B



Exhibit C

CA: Debris observed throughout the location. Refer to attached inspection photos for examples. Comply with Rule 606 and remove all debris from the location.

CA Resolution: Operator has appropriately cleaned/cleared identified debris from the location to comply with Rule 606.