

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403720396

Date Received:

03/14/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 714000492

Inspection Date: 02/29/2024

FIR Submit Date: 03/04/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

### LOCATION - Location ID: 326090

Location Name: ELMER DUNKEL GAS UNIT Number: 12NWSE County: \_\_\_\_\_  
A-N33N10W

Qtrqtr: NWSE Sec: 12 Twp: 33N Range: 10W Meridian: N

Latitude: 37.116608 Longitude: -107.881278

### FACILITY - API Number: 05-067- -00 Facility ID: 326090

Facility Name: ELMER DUNKEL GAS UNIT Number: 12NWSE  
A-N33N10W

Qtrqtr: NWSE Sec: 12 Twp: 33N Range: 10W Meridian: N

Latitude: 37.116608 Longitude: -107.881278

### CORRECTIVE ACTIONS:

1 ☒ CA# 192638

Corrective Action: Comply with rule 606.

Date: 04/03/2024

Response: CA COMPLETED

Date of Completion: 03/12/2024

Operator Comment: Unused equipment removed.

COGCC Decision: Approved pending re-inspection

COGCC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.		
<div style="background-color: #f0f0f0; padding: 2px;"><b>2</b> <input checked="" type="checkbox"/> CA# 192639</div>			
Corrective Action:		Comply with rule 606, remove and properly dispose of debris.	Date: _____
Response:		CA COMPLETED	Date of Completion: 03/12/2024
Operator Comment:		Debris removed from location.	
COGCC Decision:		Approved via an AMI	
COGCC Representative:		Per photo included in attachment provided by operator the debris has been removed.	
<div style="background-color: #f0f0f0; padding: 2px;"><b>3</b> <input checked="" type="checkbox"/> CA# 192640</div>			
Corrective Action:		Maintain equipment and clean up impacted material and dispose per Rule 906 and 1002.	Date: 03/09/2024
Response:		CA COMPLETED	Date of Completion: 03/12/2024
Operator Comment:		Impacted surface material cleaned and removed.	
COGCC Decision:		Approved pending re-inspection	
COGCC Representative:		Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.	
<div style="background-color: #f0f0f0; padding: 5px;"><b>OPERATOR COMMENT AND SUBMITTAL</b></div>			
Comment:		CA completed. See attached completion photos.	
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.			
Print Name: Gabby Riley		Signed: _____	
Title: Permitting Specialist I		Date: 3/14/2024 5:42:37 PM	

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403720396	FIR RESOLUTION SUBMITTED
403720406	Elmer Dunkle A1; CA completion photos

Total Attach: 2 Files