

State of Colorado  
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403722857

Receive Date:

Report taken by:

## Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECOM is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

## OPERATOR INFORMATION

Name of Operator: PETROSHARE CORPORATION	Operator No: 10454	Phone Numbers
Address: 9635 MAROON CIRCLE #400		Phone: (303) 894-2100
City: ENGLEWOOD	State: CO	Zip: 80112
Contact Person: James Hix - East OWP EPS	Email: james.hix@state.co.us	Mobile: (303) 905-5341

## PROJECT, PURPOSE &amp; SITE INFORMATION

## PROJECT INFORMATION

Remediation Project #: 26162 Initial Form 27 Document #: 403180509

## PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☐ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☒ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☒ Other: UPRR Wagner 12-19 (OWP) Wellhead (Loc # 320189)/ (UPRR) Wagner 12-19 Tank Battery (Loc #479190)

## SITE INFORMATION

Yes Multiple Facilities

Facility Type: WELL	Facility ID:	API #: 001-08361	County Name: ADAMS
Facility Name: (UPRR) WAGNER (OWP) 12-19	Latitude: 39.951662	Longitude: -104.599280	
** correct Lat/Long if needed: Latitude:		Longitude:	
QtrQtr: SWNW	Sec: 19	Twp: 1S	Range: 64W Meridian: 6 Sensitive Area? Yes

Facility Type: LOCATION	Facility ID: 479190	API #:	County Name: ADAMS
Facility Name: (UPRR) WAGNER 12-19 Tank Battery	Latitude: 39.951140	Longitude: -104.602510	
** correct Lat/Long if needed: Latitude:		Longitude:	
QtrQtr: Lot 1	Sec: 19	Twp: 1S	Range: 64W Meridian: 6 Sensitive Area? No

## SITE CONDITIONS

General soil type - USCS Classifications ML

Most Sensitive Adjacent Land Use Rural Residential

Is domestic water well within 1/4 mile? Yes

Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? No

### **Other Potential Receptors within 1/4 mile**

Water Wells: There are 10 DWR permitted water wells within 1/4-mile of the (UPRR) Wagner 12-19 Tank Battery Location. DWR = 69 ft, Bedrock aquifer = Lower Arapahoe (Ka) (TD: 650 ft - 700+ ft), Nearest water well: ~295 ft SE, (DWR Permit #287693- expired) TD = 450 ft (Bedrock aquifer = Upper Arapahoe), Estimated depth to groundwater 240 ft to 440 ft (DWR Permit #945876) Static Water Level = 110 ft, Top of Perf Casing: 260 ft; Surface Water: None, NWI mapped Freshwater Emergent wetlands ~450 ft SE, CPW Mapped HPH: None; Residential Building Units (RBU) 8 w/in 1/4-mile: nearest RBU ~350 ft SE; ~370 ft SW

## SITE INVESTIGATION PLAN

### TYPE OF WASTE:

- ☒ E&P Waste      ☐ Other E&P Waste      ☐ Non-E&P Waste
- ☒ Produced Water      ☐ Workover Fluids
- ☒ Oil      ☐ Tank Bottoms
- ☐ Condensate      ☐ Pigging Waste
- ☐ Drilling Fluids      ☐ Rig Wash
- ☐ Drill Cuttings      ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

### DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	SOILS	UNKNOWN	VISUALLY/FIELD SCREENING/ANALYTICAL

### INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

The Petroshare Corp. - (UPRR) Wagner (OWP) #12-19 well and Tank Battery are in the ECMC (f.k.a. COGCC) Orphaned Well Program. The well will be plugged and abandoned ("PA") and the associated On-location and Off-location flowlines and tank battery equipment will be decommissioned or removed. No initial actions or emergency response measures have been implemented at the location.

### PROPOSED SAMPLING PLAN

#### Proposed Soil Sampling

- ☒ Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Grab soil samples will be collected from areas most likely to exhibit E&P Waste impacts. Soil samples will be submitted for analysis of Table 915-1 parameters including organic compounds (TPH ranges C6-C36; BTEX; 1,2,4-Trimethylbenzene, 1,3,5-Trimethylbenzene, Naphthalene, PAH) and inorganic compounds (metals, soil suitability for reclamation). Visual inspection and field screening of soils will be conducted in areas surrounding the flowlines, tank battery equipment, and wellhead. Additional grab soil samples may be collected and submitted for laboratory analysis of Table 915-1 parameters based on site observations that indicate exploration and production (E&P) waste impacts.

#### Proposed Groundwater Sampling

- ☐ Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

Groundwater is not expected to be encountered at this site; therefore, groundwater samples are not expected to be collected as part of this investigation.

#### Proposed Surface Water Sampling

- ☐ Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

Surface water samples are not expected to be collected as part of this investigation.

### Additional Investigative Actions

- ☐ Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

Additional alternative investigative actions are not expected to be performed during this initial Site Investigation Plan.

## SITE INVESTIGATION REPORT

### SAMPLE SUMMARY

#### Soil

Number of soil samples collected 9

Number of soil samples exceeding 915-1 2

#### NA / ND

-- Highest concentration of TPH (mg/kg) 5482

-- Highest concentration of SAR 4.03

Was the areal and vertical extent of soil contamination delineated? No

BTEX > 915-1 No

Approximate areal extent (square feet) 2550

Vertical Extent > 915-1 (in feet) 5

#### Groundwater

Number of groundwater samples collected 0

Highest concentration of Benzene (µg/l)

Was extent of groundwater contaminated delineated? No

Highest concentration of Toluene (µg/l)

Depth to groundwater (below ground surface, in feet)

Highest concentration of Ethylbenzene (µg/l)

Number of groundwater monitoring wells installed

Highest concentration of Xylene (µg/l)

Number of groundwater samples exceeding 915-1

Highest concentration of Methane (mg/l)

#### Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

### OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

### REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

#### SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

The (UPRR) Wagner (OWP) #12-19 and (UPRR) Wagner 12-19 Tank Battery are in the ECMC Orphaned Well Program. The (UPRR) Wagner (OWP) #12-19 well will be plugged and abandoned (PA). Production equipment and flowlines associated with this well and associated Location will be removed or decommissioned.

#### REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

If exploration and production (E&P) waste impacted soils are encountered, the impacted materials will be excavated, temporarily stockpiled on location pending disposal at an offsite commercial disposal facility. A third party consultant will field screen soils and collect soil samples for laboratory analysis of Table 915-1 parameters.

#### Soil Remediation Summary

☐ In Situ

☐ Ex Situ

Bioremediation ( or enhanced bioremediation )

Excavate and offsite disposal

Chemical oxidation

If Yes: Estimated Volume (Cubic Yards)

Air sparge / Soil vapor extraction

Name of Licensed Disposal Facility or COGCC Facility ID #

Natural Attenuation

Excavate and onsite remediation

Other

Land Treatment

\_\_\_\_\_ Bioremediation (or enhanced bioremediation)

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Other \_\_\_\_\_

### **Groundwater Remediation Summary**

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Air sparge / Soil vapor extraction

\_\_\_\_\_ Natural Attenuation

\_\_\_\_\_ Other \_\_\_\_\_

### **GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

## REMEDIATION PROGRESS UPDATE

### PERIODIC REPORTING

#### Approved Reporting Schedule:

☐ Quarterly☐ Semi-Annually☐ Annually☐ Other

#### ☒ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☒ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

#### Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☐ Other

### Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Operator anticipates the remaining cost for this project to be: \$

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation?

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project?  No

If YES:

☐ Compliant with Rule 913.h.(1).☐ Compliant with Rule 913.h.(2).☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards?

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards?

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### **RECLAMATION PLANNING**

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be performed in accordance with COGCC 1000 Series Rules and will be addressed during a separate phase of the OWP work.

Is the described reclamation complete? \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim ☐ Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

### **SITE RECLAMATION DATES**

Proposed date of commencement of Reclamation. \_\_\_\_\_

Proposed date of completion of Reclamation. \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### **PRIOR DATES**

Date of Surface Owner notification/consultation, if required. \_\_\_\_\_

Actual Spill or Release date, or date of discovery. \_\_\_\_\_

### **SITE INVESTIGATION DATES**

Date of Initial Actions described in Site Investigation Plan (start date). \_\_\_\_\_

Proposed site investigation commencement. 10/17/2022

Proposed completion of site investigation. \_\_\_\_\_

### **REMEDIAL ACTION DATES**

Proposed start date of Remediation. \_\_\_\_\_

Proposed date of completion of Remediation. \_\_\_\_\_

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☐ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

\_\_\_\_\_

**OPERATOR COMMENT**

The PETROSHARE CORPORATION - 10454 (UPRR) WAGNER #12-19 (OWP) oil and gas well (API #05-001-08361), (UPRR) WAGNER-61S64W 19SWNW (Location ID #320189), and remote (UPRR) WAGNER 12-19 Tank Battery (Location ID #49190) are in the ECMC Orphaned Well Program. This supplemental Form 27 presents the site investigation report for the wellhead, off-location flowline, and the tank battery decommissioning sampling. A historic spill/release #484689 was discovered associated with the dump line south of the separator at the tank battery location. Petroleum contamination was observed above the ECMC Table 915-1 residential and protection of groundwater soil screening levels (SSL). Site investigation and remediation activities will proceed under Remediation Project #26162.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: James Hix

Title: East OWP EPS

Submit Date: \_\_\_\_\_

Email: james.hix@state.co.us

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

Remediation Project Number: 26162

**COA Type****Description**

0 COA	

**Attachment Check List**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

403722948	SITE INVESTIGATION REPORT
-----------	---------------------------

Total Attach: 1 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)