

Interim Reclamation and Stormwater Inspection

March 11 , 2024

Operator: Wiepking Fullerton Energy LLC- #96340

Location ID: 433700

Inspection Document #: 709400946

Lincoln County, CO

NESW Section 24 T10S R56W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MA State #4
Location ID: 433700



Photo 1. Photo taken of location sign.



Photo 2. Photo taken facing east of wellhead.



Inspection Photos
Location Name: MA State #4
Location ID: 433700



Photo 3. Photo taken facing west of vegetation in the interim reclamation area.



Photo 4. Photo taken facing north of s vegetation in the interim reclamation area.

Inspection Photos
Location Name: MA State #4
Location ID: 433700



Photo 5. Photo taken facing east of vegetation in the interim reclamation area.



Photo 6. Photo taken facing east of vegetation debris and secondary contaminants without wildlife protection.



Photo 7. Photo taken facing southeast of stained soil around wellhead.



Photo 8. Photo taken facing southeast of vegetation in the interim reclamation area.



Photo 11. Photo taken facing east of tank battery sign



Photo 12. Photo taken facing east of tank battery.