

Interim Reclamation and Stormwater Inspection

March 12 , 2024

Operator: Wiepking Fullerton Energy LLC- #96340

Location ID: 436580

Inspection Document #: 709400956

Lincoln County, CO

SWNW Section 19 T10S R55W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Aloha Mula #16
Location ID: 436580



Photo 1. Photo taken of location sign.



Photo 2. Photo taken facing east of wellhead.



Inspection Photos
Location Name: Aloha Mula #16
Location ID: 436580



Photo 3. Photo taken facing northeast of stained soil around wellhead.



Photo 4. Photo taken facing southeast of mowed vegetation in interim reclamation area.

Inspection Photos
Location Name: Aloha Mula #16
Location ID: 436580



Photo 5. Photo taken facing northwest of vegetation in interim reclamation area.



Photo 6. Photo taken facing north of vegetation in interim reclamation area.



Inspection Photos
Location Name: Aloha Mula #16
Location ID: 436580



Photo 7. Photo taken facing south of vegetation in interim reclamation area.



Photo 8. Photo taken facing southeast of vegetation in interim reclamation area and improperly installed wattle.

Inspection Photos
Location Name: Aloha Mula #16
Location ID: 436580



Photo 9. Photo taken facing south of tank battery sign



Photo 10. Photo taken facing south of tank battery.