

# Interim Reclamation and Stormwater Inspection

March 12 , 2024

Operator: Wiepking Fullerton Energy LLC- #96340

Location ID: 451940

Inspection Document #: 709400958

Lincoln County, CO

SWSW Section 18 T10S R55W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Raptor #16  
Location ID: 451940




Photo 1. Photo taken of location sign.



Photo 2. Photo taken facing west of wellhead.



Inspection Photos  
Location Name: Raptor #16  
Location ID: 451940



**Photo 3.** Photo taken facing northeast of secondary containment lacking wildlife protection.



**Photo 4.** Photo taken facing northeast of secondary containment **with** wildlife protection.

Inspection Photos  
Location Name: Raptor #16  
Location ID: 451940



**Photo 5.** Photo taken facing northwest of stained soil around equipment. .



**Photo 6.** Photo taken facing north of stained soil around secondary containment and equipment.

Inspection Photos  
Location Name: Raptor #16  
Location ID: 451940



**Photo 7.** Photo taken facing north of mowed vegetation in interim reclamation area.



**Photo 8.** Photo taken facing south of vegetation in interim reclamation area.

Inspection Photos  
Location Name: Raptor #16  
Location ID: 451940



Photo 9. Photo taken facing east of tank battery sign



Photo 10. Photo taken facing northeast of tank battery.