

Interim Reclamation and Stormwater Inspection

March 12 , 2024

Operator: Wiepking Fullerton Energy LLC- #96340

Location ID: 436130

Inspection Document #: 709400964

Lincoln County, CO

SWNE Section 23 T10S R56W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Big Wanmum #4
Location ID: 436130



Photo 1. Photo taken of location sign.



Photo 2. Photo taken facing east of wellhead.



Inspection Photos
Location Name: Big Wanmum #4
Location ID: 436130




Photo 3. Photo taken facing northeast of stained soil around wellhead.



Photo 4. Photo taken facing east of secondary containment without wildlife protection.



Inspection Photos
Location Name: Big Wanmum #4
Location ID: 436130



Photo 5. Photo taken facing southeast of vegetation in the interim reclamation area.



Photo 6. Photo taken facing northeast of vegetation in the interim reclamation area.

Inspection Photos
Location Name: Big Wanmum #4
Location ID: 436130



Photo 7. Photo taken facing northwest of vegetation in the interim reclamation area.



Photo 8. Photo taken facing west of vegetation in the interim reclamation area.

Inspection Photos
Location Name: Big Wanmum #4
Location ID: 436130



Photo 11. Photo taken facing east of tank battery sign



Photo 12. Photo taken facing east of tank battery.