

WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)

121 - 07072

Well Name 4-2 Xenia
Operator Kingwood
Location NENE 11-2N-54W
Field Xenia

API Number 05 - 121 -
Permit #
County Washington
Inspector EBB



AL/PA/DA Inspection Results:

Well Status:

SCANNED

Pass(Y) ☒ Fail(N) ☐ Date 7/24/64 ND ☐ DG ☐ WO ☐ PR ☐ SI ☐ TA ☐

Date of Inspection Before/During Drilling

Surf. Csg. Size Setting Depth Cmt. Vol. WOC time

Consistent with APD casing Program? YES ☐ NO ☐ Returns

Rig BOP'S Stage Tool Depth Cmt. Vol.

Date of Inspection Before/During/After Completion

Prod. Csg. Set? Completion Rig/Activity

Drilling Pits: Closed ☐ Open ☐ Wellhead Installed: Sign: Yes ☐ No ☐

Tank ID: Yes ☐ No ☐ N/A ☐ Skim Tank/Pit: Prod. Tanks: () BBLS

Equipment Meter Run: Yes ☐ No ☐

Bradenhead Press: Fluid: No ☐ Yes ☐ Type Well Cat.

AL/PA/DA Inspection

Date Plugged: 4-8-64

Date Permit Expired:

Hole Plugged: Yes ☐ No ☐

Pits Backfilled: Yes ☐ No ☐

Material Buried: Yes ☐ No ☐ N/A ☐

Site Clean: Yes ☐ No ☐

Bond Release OK: Yes ☐ No ☐ Fed ☐

Hole Marker: Yes ☐ No ☐

Date of Safety/Status Inspection

Comments: Historical



Violations: Yes ☐ No ☒ Notice Sent: Yes ☐ No ☐ Date Sent: