

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NENW

Location ID: 335458

Date: 3/15/2024



Location Entrance – Photo #09883



Wellheads – Photo #09984

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NENW

Location ID: 335458

Date: 3/15/2024



Wellheads – Photo #09985

Separators – Photo #09887

