

# Interim Reclamation and Stormwater Inspection

March 12 , 2024

Operator: P O & G Operating LLC- #10634

Location ID: 324940

Inspection Document #: 709400972

Lincoln County, CO

NENE Section 34 T11S R51W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Bledso 1-34X  
Location ID: 324940



**Photo 1.** Photo taken of location sign. Information needs to be legible.



**Photo 2.** Photo taken facing east of wellhead.





Inspection Photos  
Location Name: Bledso 1-34X  
Location ID: 324940



**Photo 3.** Photo taken facing southeast of stained soil from spill onsite.



**Photo 4.** Photo taken facing east of secondary containment without wildlife protection, and stained soil from spill onsite.





Inspection Photos  
Location Name: Bledso 1-34X  
Location ID: 324940



**Photo 5.** Photo taken facing southwest of stained soil leading into interim reclamation from pumpjack. Spill outlined in red.



**Photo 6.** Photo taken facing east of terminus of stained soil from a spill at the jumpjack.





Inspection Photos  
Location Name: Bledso 1-34X  
Location ID: 324940



Mar 12, 2024 at 1:13:06 PM  
County Road B  
Flagler CO 80815  
United States



Mar 12, 2024 at 1:13:58 PM  
Flagler CO 80815  
United States

**Photo 7.** Photo taken facing northwest of wellhead and stained soil.

**Photo 8.** Photo taken facing west of mowed vegetation in the interim reclamation area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 709400972



Inspection Photos  
Location Name: Bledso 1-34X  
Location ID: 324940



**Photo 9.** Photo taken facing southwest of tank battery.



**Photo 10.** Photo taken facing southeast at tank battery pad and erosion crossing the access road and along side tank battery berm. indicated by red arrow.



Inspection Photos  
Location Name: Bledso 1-34X  
Location ID: 324940



**Photo 11.** Photo taken facing south at tank battery pad and erosion crossing the access road and along side tank battery berm.



**Photo 12.** Photo taken facing southwest at tank battery pad, of bare soil and stormwater erosion.