

Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768



Unused equipment storage



Missing required information

Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768



No label



Oily waste and soil staining

**Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768**



Oily waste



Soil staining

**Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768**



Oily waste



Oily waste and soil staining

**Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768**



Mar 18, 2024 at 1:44:07 PM

Lack of Stormwater BMP maintenance and vehicle tracking



Mar 18, 2024 at 1:47:38 PM

Vehicle tracking on to Highway 40

**Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768**



Location from Northwest corner



Location from Southwest corner

**Beeman Oil & Gas Inc
Elk Springs Unit 3
Location ID: 311768**



Location from Southeast corner



Location from Northeast corner