

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17NWSE

Location ID: 335587

Date: 3/15/2024



Location Entrance – Photo #09920



Wellheads – Photo #09921

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17NWSE

Location ID: 335587

Date: 3/15/2024



Separators – Photo #09922



Tank Battery – Photo #09923

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17NWSE

Location ID: 335587

Date: 3/15/2024



Open-Ended Load Line – Photo #09925

