

Inspection Photos

API: 099-06059

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 3/15/2024

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast at the location. The abandoned pipe riser has been removed. Will need to verify crop cover once replanted.



Inspection Photos



Photo 2. Facing west at the location. The abandoned pipe riser has been removed. Will need to verify crop cover once replanted.

