

Inspection Photos

API: 099-06066

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 3/15/2024

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north at the location. The equipment has been removed.



Inspection Photos



Photo 2. Facing northeast at the location. The equipment has been removed



Inspection Photos



Photo 3. Facing southeast at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 099-06066 | Date: 3/15/2024